20 May 2025, 11:00 (Europe/Berlin)

syniotec

Handover Report

Handover ID

RC15484BTT

Contract ID RC15484BTT

Type Hand In

Rental Company	Transport Provider	Customer
Max Mustermann	John Doe	Max Mustermann
GmbH Große Mode	GmbH Holidayquelle	GmbH Reisefokus

Overview

	Product	Name	Booking Dates	Quantity
#1	Crawler excavator	Volvo F504	01.01.2028 14:42 – 02.02.2029 16:48	1

All field types

Hydraulic pipe problem
Back side

Last Answer Back side

Problem date
01.01.2028

Last Answer 01.01.2027

Problem time
14:42

Last Answer 09:15

Hydraulic pipe problem
Yes




Additional information * The damage always indicates the failure or impairment of a machine or technical system. Machine damage can take many forms and often has a significant impact on efficiency.

Last Answer Yes
Additional information * The damage always indicates the failure or impairment of a machine or technical system. Machine damage can take many forms and often has a significant impact on efficiency.




Hydraulic pipe problem
No

Additional information * The damage always indicates the failure or impairment of a machine or technical system. Machine damage can take many forms and often has a significant impact on efficiency.

Last Answer Yes

Problem rating
3/5

Additional information * The damage always indicates the failure or impairment of a machine or technical system. Machine damage can take many forms and often has a significant impact on efficiency.

Last Answer **3/5**
Additional information * The damage always indicates the failure or impairment of a machine or technical system. Machine damage can take many forms and often has a significant impact on efficiency.

Problem range
From 10% • To 50%

Last Answer From 10% • To 50%

Problem description
The damage always indicates the failure or impairment of a machine or technical system. Machine damage can take many forms and often has a significant impact on efficiency.

Last Answer
The damage always indicates the failure or impairment of a machine or technical system. Machine damage can take many forms and often has a significant impact on efficiency.

Problem chooser
Row 2

Last Answer Row 2

Problem slider
50%

Additional information * The damage always indicates the failure or impairment of a machine or technical system. Machine damage can take many forms and often has a significant impact on efficiency.

Last Answer 30%

Problem checks
Second option
Third option

Last Answer
First option
Third option

Problem image



Last Answer 

Problem file
File name.pdf

Last Answer File name.pdf

Problem switcher
No
Engine stops when the switch is off

Last Answer No
Engine stops when the switch is off

Problem dropdown
No

Last Answer No

Problem count
12

Last Answer 12

Groups and photos

Problem group

General	Complete	Condition/function OK?
First question	Yes	Okay

Last Answer No
Additional information * Small scratch on the left side, already known at hand out.

Second question	Not relevant	Okay

Last Answer Not relevant

Third question	Answer 6	Not okay

Last Answer Answer 2

Fourth question	No	Not okay

Additional information * The damage always indicates the failure or impairment of a machine or technical system. Machine damage can take many forms and often has a significant impact on efficiency.

Last Answer No previous answer

Problem gallery

Problem 4



Last Answer 

Problem 5



Last Answer 

Problem 6



Last Answer 

Problem AI

Problem 1



Last Answer



Problem 2



Last Answer



Rental Company

Max Mustermann

GmbH Große Mode

Transport Provider

John Doe

GmbH Holidayquelle

Customer

Max Mustermann

GmbH Reisefokus

max.mustermann@reisefokus.de

20 May 2025, 11:00 (Europe/Berlin)

Handover Report RC15484BTT

syniotec
A brand of Sharemac GmbH

Address: Am Wall 146
City: Bremen
Postcode: 28195
Country: Germany

T +49 421 83679700
M info@syniotec.com
www.syniotec.com

VAT ID: DE316314130
Register no.: HRB 33169

Bank: Deutsche Bank
BIC/SWIFT: DEUTDEFFXXX
IBAN: DE34 5001 0517 3163 9812 79

Management: Manuel Kimanov

Terms and conditions
“Terms and Conditions” is the document governing the contractual relationship between the provider of a service and its user. On the web, this document is often also called “Terms of Service” (ToS), “Terms of Use”, EULA (“End-User License Agreement”), “General Conditions” or “Legal Notes”.