20 May 2025, 11:00 (Europe/Berlin)

syniotec

Handover Report

Handover ID

RC15484BTT

Contract ID RC15484BTT

Type Hand In

Rental Company	Transport Provider	Customer
Max Mustermann	John Doe	Max Mustermann
GmbH Große Mode	GmbH Holidayquelle	GmbH Reisefokus

Overview

	Product	Name	Booking Dates	Quantity
#1	Crawler excavator	Volvo F504	01.01.2028 14:42 – 02.02.2029 16:48	1

Rental information

Warehouse
Halensee Warehouse

Last Answer Halensee Warehouse

Rental ID
RC15484BTT

Last Answer RC15484BTT

Company/customer
Reisebüro GmbH

Last Answer Reisebüro GmbH

Place of use
Bremen Roadworks

Last Answer Bremen Roadworks

Tank level
65%



Last Answer 90%



Attachments

Attachment 1
Scratches on front mirror




Last Answer
Scratches on front mirror



Attachment 2 Technical check in PDF

Document 14.02.2020

Document 14.02.2020

Last Answer Document 14.02.2020

General information

UVV
26.01.2021

Last Answer 26.01.2021

Working hour
8:00 AM

Last Answer 7:30 AM

Cleaning in order?
Yes

Last Answer Yes

Question group

Group

General	Complete	Condition/function OK?
1.1 General operating licence / registration certificate	Yes	Not okay

Additional information * The damage always indicates the failure or impairment of a machine or technical system. Machine damage can take many forms and often has a significant impact on efficiency.

Last Answer Yes Condition Okay
Additional information * Small scratch on the left side, already known at hand out.



1.2 Operating instructions	Not relevant	Okay

Last Answer Not relevant Condition Okay

1.3 Hazard assessment	No	Not okay

Last Answer Yes Condition Okay

1.4 Last test certificate	Yes	Okay

Last Answer Yes Condition Okay

1.5 Type plate / CE marking	Not relevant	Okay

Last Answer Not relevant Condition Okay

1.6 Declaration of conformity	No	Not okay

Last Answer No Condition Not okay

1.7 Warning signs / information plates	Not relevant	Okay

Last Answer Not relevant Condition Okay

1.8 Last test certificate	No	Okay

Last Answer No Condition Okay

1.9 Type plate / CE marking	Not relevant	Okay

Last Answer Not relevant Condition Okay

1.10 Last test certificate	No	Not okay

Last Answer No Condition Not okay

1.11 Type plate / CE marking	Not relevant	Okay

Last Answer Not relevant Condition Okay

1.12 Last test certificate ✓ Yes Okay

Additional information * The damage always indicates the failure or impairment of a machine or technical system. Machine damage can take many forms and often has a significant impact on efficiency.



Last Answer ✓ Yes Condition Okay

Additional information * The damage always indicates the failure or impairment of a machine or technical system. Machine damage can take many forms and often has a significant impact on efficiency.



1.13 Type plate / CE marking ⊖ Not relevant Okay

Last Answer ⊖ Not relevant Condition Okay

Lights

Headlights

✓ Yes

Last Answer ✓ Yes

Cabin lights

✗ No





Last Answer ✓ Yes



Photos

Front view



Last Answer 

Left side 45 degrees



Last Answer 

Back view



Last Answer 

Right side 45 degrees



Last Answer 

Cabin



Last Answer 

Bucket



Last Answer 

Other image



Last Answer No previous answer

360 views

360° view exterior

Exterior video.mp4

Last Answer Exterior video.mp4

360° view interior

Interior video.mp4

Last Answer Interior video.mp4

Rating

Rate the equipment

3/5

Additional information * The quick brown fox jumps over the lazy dog

Last Answer 4/5

Additional information * Clean and ready to use

Rental Company

Max Mustermann

GmbH Große Mode

Transport Provider

John Doe

GmbH Holidayquelle

Customer

Max Mustermann

GmbH Reisefokus

max.mustermann@reisefokus.de

20 May 2025, 11:00 (Europe/Berlin)

Handover Report RC15484BTT

syniotec

A brand of Sharemac GmbH

Address: Am Wall 146
City: Bremen
Postcode: 28195
Country: Germany

T +49 421 83679700
M info@syniotec.com
www.syniotec.com

VAT ID: DE316314130
Register no.: HRB 33169

Bank: Deutsche Bank
BIC/SWIFT: DEUTDEFFXXX
IBAN: DE34 5001 0517 3163 9812 79

Management: Manuel Kimanov

Terms and conditions

“Terms and Conditions” is the document governing the contractual relationship between the provider of a service and its user. On the web, this document is often also called “Terms of Service” (ToS), “Terms of Use”, EULA (“End-User License Agreement”), “General Conditions” or “Legal Notes”.