

```

[
  {
    "name": "DiagnosticsApp",
    "vehicleModel": {
      "src":
"https://github.com/COVESA/vehicle_signal_specification/releases/download/v3.0/
vss_rel_3.0.json",
      "datapoints": [
        {
          "path": "Vehicle.Cabin.Seat.Row1.Pos1.Position",
          "required": "true",
          "access": "write"
        },
        {
          "path": "Vehicle.Speed",
          "required": "true",
          "access": "read"
        },
        {
          "path": "Vehicle.Chassis.Accelerator.PedalPosition",
          "required": "true",
          "access": "read"
        },
        {
          "path": "Vehicle.IsMoving",
          "required": "true",
          "access": "read"
        },
        {
          "path": "Vehicle.Body.Windshield.Front.Wiping.System.Mode",
          "required": "true",
          "access": "write"
        }
      ]
    },
    "runtime": [
      "grpc://sdv.databroker.v1.Broker/GetDatapoints",
      "grpc://sdv.databroker.v1.Broker/Subscribe",
      "grpc://sdv.databroker.v1.Broker/SetDatapoints",
      "mqtt"
    ]
  }
]

```