



PROPERTY	ALT-042 · Altea (Alicante)
VISIT OF	14/03/2026 · 17:02 to 17:41
CARRIED OUT BY	F. L. · Domivaro
PLAN	Serenity
WEATHER	19°, clear

● 38 points checked

● 1 point to watch

● 1 quote awaiting approval

Terrace
17:04

Utility room
17:19

South shutters
17:31

Photo slot of the real report, timestamped at capture

The state of the house, point by point

The outside and the structure

- | | | |
|----|---|---------|
| 01 | Roof as visible from the ground, slipped or broken tiles | ● Fine |
| 02 | Downpipes and gutters, blockage by pine needles | ● Fine |
| 03 | Facades, new cracks, blistering paint, rising salt at the base of walls | ● Fine |
| 04 | External joinery, seals, sliding door tracks clogged with salt | ● Fine |
| 05 | Shutters and blinds, each one fully operated | ● Watch |
| 06 | Gate, pedestrian door, motor and remote battery | ● Fine |
| 07 | Terraces and balconies, drainage, loose or lifted tiles | ● Fine |

Water

- | | | |
|----|--|--------|
| 08 | Meter read and photographed, compared with the previous visit | ● Fine |
| 09 | Check for abnormal consumption with all taps closed | ● Fine |
| 10 | Main stopcock, operated to prevent seizing | ● Fine |
| 11 | Water heater, corrosion, safety group, any weeping | ● Act |
| 12 | Indoor water points, drainage, traps filled against odour backflow | ● Fine |
| 13 | Toilets, flush, silent leak in the cistern | ● Fine |
| 14 | Softener or filter if fitted, level and regeneration | ● Fine |

Electricity and air conditioning

- | | | |
|----|---|----------------|
| 15 | Consumer unit, no tripped breaker, RCD tested | ● Fine |
| 16 | Meter read and photographed | ● Fine |
| 17 | Indoor and outdoor lighting, dead bulbs reported | ● Fine |
| 18 | Air conditioning, every unit started, condensate tray checked | ● Fine |
| 19 | Air conditioning filters, fouling, cleaned if needed | ● Done on site |
| 20 | Appliances left on standby, unplugged where possible | ● Fine |

Inside and damp

- | | | |
|----|--|--------|
| 21 | Humidity measured in every room, figure recorded in the report | ● Fine |
| 22 | Check for mould behind furniture and in north facing corners | ● Fine |
| 23 | Ceilings and walls, tide marks, blistering, peeling paint | ● Fine |
| 24 | Full airing of the house for the duration of the visit | ● Fine |
| 25 | Fridge and freezer, temperature, ice build up, smell | ● Fine |
| 26 | Signs of rodents, insects, bee or wasp nests | ● Fine |
| 27 | Post collected, sorted, anything official set aside | ● Fine |

Pool and garden

- | | | |
|----|---|--------|
| 28 | Water level, topped up if needed | ● Fine |
| 29 | Pump and filtration, noise, flow, running time | ● Fine |
| 30 | Plant room, leak, damp, corrosion at the fittings | ● Fine |
| 31 | Water appearance, control photograph at every visit | ● Fine |
| 32 | Automatic watering, timer, leak on the drip line | ● Fine |
| 33 | Planting against facades and under tiles, pruning flagged if needed | ● Fine |



Passive security and paperwork

- | | | |
|----|---|--------|
| 34 | Every opening closed and locked before leaving | ● Fine |
| 35 | Alarm reset if the property has one | ● Fine |
| 36 | No key and no code left on site | ● Fine |
| 37 | Record of any visible change since the previous visit | ● Fine |
| 38 | Time stamped photographs of the sensitive points and of the meter | ● Fine |

Watch

South-west shutter: one cracked slat, no urgency. Photographed, reviewed at the next visit.

The point awaiting your approval

Water heater safety valve: seeping at the fitting. Written quote: replacement at 85 €, fitting included. No work starts without your approval.

Done on site, within the included labour

Air-conditioning filters cleaned (point 19). Traps refilled, main stop valve operated.

Report sent to the owner on 14/03/2026 at 17:42.