

CRASH LENS

Crash Analysis Report

S-VA043PR WOODMAN RD / S-VA043NP MAGN...

Location: S-VA043PR WOODMAN RD

Period: 07/05/2019 - 04/16/2025

Total Crashes: 17

Generated: 4/6/2026

17

TOTAL CRASHES

0

FATAL (K)

1

SERIOUS (A)

5.9%


K+A RATE

114

EPDO SCORE

2.4

CRASHES/YEAR



Map Legend

17 crashes mapped



Location:

S-VA043PR WOODMAN RD / S-...

Severity Distribution



Vulnerable Road Users



Collision Type Analysis

2. Angle		15 (88.2%)
9. Fixed Object - Off Roa		2 (11.8%)

Weather Conditions

Condition	Count	Percentage
1. No Adverse Condition (Clear/Clou	14	82.4%
5. Rain	3	17.6%

Light Conditions

Condition	Count	Percentage
5. Darkness - Road Not Lighted	9	52.9%
2. Daylight	8	47.1%

Day of Week Distribution



Time of Day Analysis

Peak Hour:

2:00 PM - 3:00 PM

(2 crashes)

Peak Day:

Friday

(4 crashes)

Hourly Distribution

0:00 - 5:00			6:00 - 11:00			12:00 - 17:00			18:00 - 23:00		
12AM	1	(5.9%)	6AM	1	(5.9%)	12PM	0	(0.0%)	6PM	1	(5.9%)
1AM	0	(0.0%)	7AM	1	(5.9%)	1PM	1	(5.9%)	7PM	2	(11.8%)
2AM	0	(0.0%)	8AM	0	(0.0%)	2PM	2	(11.8%)	8PM	2	(11.8%)
3AM	0	(0.0%)	9AM	0	(0.0%)	3PM	0	(0.0%)	9PM	2	(11.8%)
4AM	0	(0.0%)	10AM	0	(0.0%)	4PM	1	(5.9%)	10PM	1	(5.9%)
5AM	0	(0.0%)	11AM	1	(5.9%)	5PM	1	(5.9%)	11PM	0	(0.0%)


Yearly Distribution

Year	Crashes	Percentage	EPDO
2019	1	5.9%	1
2022	2	11.8%	32
2023	7	41.2%	59
2024	6	35.3%	21
2025	1	5.9%	1

Note: Years 2020, 2021 have no crashes in this selection.

This section presents satellite imagery and detected roadway assets within the study area.
Asset data is sourced from Mapillary street-level imagery. Engineers should verify assets through field observation.

Satellite View with Crash Locations



DATA SOURCES & LIMITATIONS

- Satellite imagery: Mapbox Satellite Streets
- Asset detection: Mapillary street-level imagery (coverage varies by location)

- Asset data represents conditions at time of imagery capture and should be verified through field observation