FAST AUTOWORLD PHILIPPINES CORPORATION

National Highway, Maguikay Mandaue City 6014

Tel. No.: 345-1233 or 420-5777

REPAIR ESTIMATE

REGISTERED OWNER: ADDRESS:		Plate No.	Chassis No.	Model Make	
		K.M. Reading	Engine No.		
00113014	ASIA UNITED LEASING AND FINAN N	FO5161 PAE	185NVIJ. B0008 . 1.300.	CC Exceed 2.2 Dst MT - 2	
	+639352523914	Date	Telefax No.	No. Of working days	
DATE HOW A	DOTAL O CENTED 17 ADD AVE PASIS OF	4816	UU CORCO VIII		

5/25/2021

DESCRIPTION OF WORKS

MOTORS

Document

Advisor

Work Detail					
	1,000 KILOMETER CHECK UP		0.00	0.00	0.00
	SERVICE MATERIALS		350.00	0.00	350.00
	CHECK AIRCON/MATERLEAK		0.00	0.00	0.08
	CHECK BRAKE LIGHT		0.00	0.00	-0.00
				Sub-Total	350,00
Parts				4	
	FILTER,OL(30)(PC(S))	1.00	473.58	0.15	402.54
	MINERAL OIL 15/440/CT-4 24LI/BX (DSL)(LT(S))	6.03	328.25	0.15	1,674,07
	GASKET,ENG O/PAN DRAIN PLUG(10)(PC(S))	1.00	127.64	0.15	108.49
				Sub Total	2,185.10
PARTS			- THE 18	ATTENDED TO	100.00
	ENGINE FLUSH		495.00	0.00	495,00
				Sub Total	495,00
			G	rossTotal	3,030.10

Not walld for legal purposes.

I hereby promise to pay the above estimate in full upon completion, subject however to adjustment to any additional repair which is overlooked in the above repair estimate.

(I is agreed that a garage fee of P80 00 per day will be charged if the subject vehicle is not claimed within 3 days from completion of the repairs

LONFORME				
	(Sign Over Printed Name)	M		
Service Estimator		Service Advisor		

Service Manager

Above quotation is based on visible defect. This is an estimate not the actual filled cost.

^{***} Replaced parts not claimed within 6 days upon released of unit shall be considered for disposal.