

RAINFALL at Worthing Broadwater 49' 2" levelCounty of SussexObserver Edwin Afted Esq.River Basin Adur + C 3

Rain Gauge, by \_\_\_\_\_


|              |      |      |      |      |      |      |      |      |      |       |        |  |
|--------------|------|------|------|------|------|------|------|------|------|-------|--------|--|
| Diameter ... |      |      |      |      |      | 5    |      |      |      |       |        |  |
| Height ..... |      |      |      |      |      | 56   |      |      |      |       |        |  |
| Altitude ... |      |      |      |      |      | 30   |      |      |      |       |        |  |
| Year ...     | 1910 | 1911 | 1912 | 1913 | 1914 | 1915 | 1916 | 1917 | 1918 | 1919  | MEANS. |  |
| January ...  |      |      |      |      | .49  | 3.63 | 1.07 | 1.09 | 3.47 | 5.15  |        |  |
| February ... |      |      |      |      | 3.14 | 3.62 | 4.77 | 1.79 | .81  | 2.43  |        |  |
| March .....  |      |      |      |      | 4.18 | .82  | 3.64 | 1.89 | 1.30 | 4.96  |        |  |
| April .....  |      |      |      |      | 1.63 | 1.15 | .57  | 1.48 | 2.39 | 2.26  |        |  |
| May .....    |      |      |      |      | .75  | 4.13 | 1.65 | .92  | 1.22 | .25   |        |  |
| June .....   |      |      |      |      | 1.02 | .49  | 2.05 | 3.40 | 1.21 | .68   |        |  |
| July .....   |      |      |      |      | 1.61 | 2.82 | .58  | 2.32 | 3.20 | 1.59  |        |  |
| August ..... |      |      |      |      | 1.19 | 2.13 | 2.75 | 4.77 | 2.29 | 3.45  |        |  |
| September .. |      |      |      |      | 1.10 | 2.37 | 1.63 | 1.25 | 5.42 | 1.18  |        |  |
| October ...  |      |      |      |      | 2.62 | 3.37 | 4.34 | 3.71 | 1.67 | .42   |        |  |
| November ..  |      |      |      |      | 3.50 | 2.82 | 4.03 | 1.38 | 1.84 | 2.54  |        |  |
| December...  |      |      |      |      | 6.63 | 7.57 | 4.51 | 2.05 | 2.24 | 5.28  |        |  |
| TOTALS ...   |      |      |      |      | 2786 | 3545 | 3159 | 2605 | 2682 | 30.19 |        |  |

1914 read V.16 cut? K.16

1914 House  
WallsN  
W  
E

1910 average rejected from Survey as being 2" low

Worthing Stat.



g. placed at 5'6" in 1913 because when at 1' it was sheltered by walls. The stand is concreted into the ground. S.A. 26. V. 16.

| Date. | Lat. N. | Long. | Railway Station. | Distance. | Direction. | Church.    | Distance. | Direction. |
|-------|---------|-------|------------------|-----------|------------|------------|-----------|------------|
| 1914  | 50.48   | 0.23w | Worthing         | 1/4 mi    | S          | Broadwater | 1/4 mi    | N.E.       |