

RAINFALL AT *East Budleigh Otterton Ticeago*

Lat. Lon. County of *S Devon*
 Rain Gauge, by Observer *P. H. Mackworth Drake*

Are - 7.

Diameter ..						5					
Height						10					
Altitude ..						80					
Year	1900	1901	1902	1903	1904	1905	1906	1907	1908	1909	MEANS.
January ..						1.33	5.57	.98	.71	1.42	
February ..						.87	3.40	1.46	1.61	.41	
March						4.18	1.20	.59	2.98	5.19	
April						2.63	1.08	4.89	2.52	1.69	
May						.61	2.73	2.48	2.08	1.17	
June						2.75	2.27	2.00	.66	2.82	
July						.43	.99	1.84	1.47	2.33	
August						3.99	1.17	1.35	3.84	2.08	
September ..						2.03	1.12	.61	2.65	1.39	
October						2.51	4.49	6.80	3.32	5.18	
November ..						4.58	2.74	2.73	1.06	.43	
December ..						.78	1.53	4.64	3.02	5.17	
TOTALS ..						26.69	28.29	30.37	25.92	29.28	

1905 Otterton Church 250 yards W
 East Budleigh Station 400 W
 House 29 ft high 54 ft E
 Holly tree 46. 66. S S W
 Small tree N
 1906 Jan 17th gauge moved 25 ft N N E

RAINFALL at East Budleigh Otterton VicarageCounty of South DevonObserver Rev R SeymourRiver Basin Cye & C 7

Rain Gauge, by _____

Diameter ...	5										
Height	1 0		0 7								
Altitude ...	62		80								
Year ...	1910	1911	1912	1913	1914	1915	1916	1917	1918	1919	MEANS.
January ...	3.51	.91	4.15	6.93		2.80					
February ...	4.26	1.43	3.25	1.02		5.55					
March	.62	2.51	4.68	3.06		.54					
April	2.33	1.60	.15	3.30		.74					
May	2.67	1.55	1.77	2.54		2.03					
June	1.94	2.42	6.55	.43		2.03					
July	2.70	.52	2.35	.38		3.76					
August	4.94	.55	6.09	1.19		3.17					
September ..	.39	1.37	1.07	2.32		.90					
October ...	3.84	3.58	4.38	4.09		7.06					
November ..	4.45	4.03	1.58	3.26		2.52					
December ...	6.60	8.78	4.27	2.23		7.12					
TOTALS ...	38.25	29.25	39.29	31.05	N.R.	38.52	N.R.				

House 31 ft. high 39 ft. E
 Hedge 33 " N
 72 " W
 Wall 60 " S

+ Inspected

Date.	Lat. N.	Long.	Railway Station.	Distance.	Direction.	Church.	Distance.	Direction.
910	51	3	E Budleigh	440 yds 1/4 m	N W	Otterton	150 yds 200 yds	N W W