

RAINFALL at Mayfield Limerick CollegeCounty of SurreyObserver Brother Aloysius Aloysius
1917, 2, HollingheadRiver Basin Rother 6

Sunderland Rain Gauge, by _____

Diameter ...						6	5				
Height						1	0				
Altitude ...						400					
Year ...	1910	1911	1912	1913	1914	1915	1916	1917	1918	1919	MEANS.
January ...						^{mean} 2.79	1.72	2.83	3.71	6.64	
February ...						5.82	3.71	1.72	1.55		
March						.76	3.92	3.04	1.31		
April						1.68	1.17	4.40	3.40		
May						3.75	1.90	3.64	1.29		
June						.35	2.70	3.58	1.43		
July						2.41	.77	5.39	5.41		
August						1.64	2.48	9.96	1.54		
September ..						2.32	1.11	1.54	6.39		
October ...						1.51	4.62	3.61	2.76		
November ..						2.12	4.55	2.75	2.89		
December...						6.46	6.42	2.90	3.18		
TOTALS ...						31.61	35.07	45.38	34.86		

9.15 Jan First four days missing
 Ice 6 ft high 12 ft E
 Building 100. 42. NW
 2 Big.

1917 wrong glass used, greater part defective

Date.	Lat. N.	Long. E	Railway Station.	Distance.	Direction.	Church.	Distance.	Direction.
	51.2	15.6	Mayfield	1.42	SW	St Dunstan	1.10	SW

RAINFALL at Mayfield Xaverian College

20

County of LeicesterObserver Rev. J. A. HollingsheadRiver Basin Roche - 6

Rain Gauge, by _____

Diameter ...			5								
Height			1 0								
Altitude ...			400								
Year	1920	1921	1922	1923	1924	1925	1926	1927	1928	1929	MEANS.
January ...			4.54								
February ...			3.37								
March			2.40								
April			3.49								
May			79								
June			1.26								
July			3.39								
August			2.75								
September...			2.16								
October			1.47								
November...			1.75								
December...			3.20								
TOTALS...			30.57	NR	NR #						

Position of Station on reduced Ordnance Survey
Map, 2 miles to 1 inch Series

No. of Map _____

Reference No. _____

Date.	Lat. N.	Long.	Railway Station.	Distance from gauge	Direction	Parish Church.	Distance from gauge	Direction