Electrical Maintenance Report

Test uhhujh

Work Order: Test IR 2

None
None, DE None

EG-ACME

November 6th, 2026

Table of Contents

Foreword **3**

Condition Assessment **4**

Results Summary **5**

Electrical Inventory List **6**

Issues

Thermal Anomaly on A2 7

Thermal Anomaly on A1 8

Assets

GEN 3 9

A2 10

Panel 1 12

UTIL 2 13

A1 14

Foreword

Thermographic analysis identifies potential heat-related issues that can impact equipment performance and safety. Elevated temperatures indicate problems such as loose connections, overloaded circuits, or degraded components. Addressing these anomalies helps prevent unscheduled outages, equipment failures, and safety hazards, ensuring the reliability and efficiency of the system.

To interpret the temperature differences (ΔT) effectively, three comparison methods are used:

- **Similar Method:** Compare the temperatures of similar components operating under similar load conditions to identify discrepancies.
- **Ambient Method:** Compare the temperature of a component to the surrounding ambient air temperature to detect unusual heat patterns.

The following table outlines the recommended actions based on temperature differences identified during a thermographic survey for the Similar and Ambient comparison criteria. Indirect Anomalies are highly situational, and thus left up to the discretion of the qualified Thermographer to identify and classify appropriately.

ΔT - Similar Method	ΔT - Ambient Method	Thermal Classification	Recommended Corrective Action
1.8 - 5.4 °F 1 - 3 °C	1.8 - 18.0 °F 1 - 10 °C	Nominal	Possible deficiency; warrants investigation
5.5 - 27.0 °F 4 - 15 °C	18.1 - 36.0 °F 11 - 20 °C	Intermediate	Indicates probable deficiency; repair as time permits
—	36.1 - 72.0 °F 21 - 40 °C	Serious	Monitor until corrective measures can be accomplished
> 27.0 °F > 15 °C	> 72.0 °F > 40 °C	Critical	Major discrepancy; repair immediately

More information about Infrared Thermography can be found in NETA® MTS, Table 100.18.

Certifier: shubham.goswami+acme@egalvanic.com

Condition Of Maintenance NFPA 70B

Serviceable - Equipment that passes all tests and is electrically and mechanically sound shall be designated as serviceable.

Limited Service - Equipment that has problems that are not detrimental to the protective operation or characteristics of the equipment shall be designated as limited service.

Non-Serviceable - Equipment that has a problem that is detrimental to the proper electrical or mechanical operation of the equipment shall be designated as non-serviceable. Access to non-serviceable equipment by unqualified persons shall be restricted.

SERVICEABLE	LIMITED SERVICE	NON-SERVICEABLE

Results Summary

In total, the field technician(s) inspected 5 items, and in so doing, identified 2 issues of the following type(s):

- 2 Thermal Anomaly

Of these issues, the thermographer was able to resolve 0, leaving a total of 2 open issues at your site.

Asset Name	Issue Type	Issue Status	Priority
A2	Thermal Anomaly	OPEN	MEDIUM
A1	Thermal Anomaly	OPEN	MEDIUM

Camera: FLIR-IND

Electrical Inventory List

Unknown Building				
Location	**Asset Name**	**Asset Class**	**Serviceability**	**QR code**
–	GEN 3	Generator	**N/A**	TU-CHG0556
–	UTIL 2	Utility	**N/A**	TU-A496563
–	Panel 1	Series Reactor	**N/A**	TU-DBL0556
–	A1	Panelboard	**N/A**	
–	A2	Panelboard	**N/A**	

Thermal Anomaly on A2 - Critical


MEDIUM

BASIC INFO			
Asset Name:	A2	**Location:**	None – None – None
Asset Class:	Panelboard	**QR Code**	None
Status	Open	**Proposed Resolution:**	None


Problem Description -	☐ Immediate Hazard	☐ Customer Notified

Thermal Anomaly detected on A2

IR PHOTOS



H3_visual



H3

THERMAL ANALYSIS			
Problem Location:		**Reference Temperature:**	55 °F
Measured Temperature:	44 °F	**ΔT:**	11 °F
Severity Criteria:		**Severity:**	Critical

Thermal Anomaly on A1 - Intermediate

MEDIUM

BASIC INFO			
Asset Name:	A1	**Location:**	None – None – None
Asset Class:	Panelboard	**QR Code**	None
Status	Open	**Proposed Resolution:**	None

Problem Description -	☐ Immediate Hazard	☐ Customer Notified
Thermal Anomaly detected on A1		

THERMAL ANALYSIS			
Problem Location:	22	**Reference Temperature:**	33 °F
Measured Temperature:	11 °F	**ΔT:**	22 °F
Severity Criteria:		**Severity:**	Intermediate

GEN 3

BASIC INFO			
Asset Name:	GEN 3	**Condition Designation:**	N/A
Asset Class:	Generator	**Serviceability:**	N/A
Location:	None – None – None		

PHOTOS


COMMENTS: N/A

A2

BASIC INFO			
Asset Name:	A2	**Condition Designation:**	N/A
Asset Class:	Panelboard	**Serviceability:**	N/A
Location:	None – None – None		

PHOTOS

IR PHOTOS




H5_visual




H5




H4_visual



H4



H3_visual



H3

COMMENTS: N/A

Panel 1

BASIC INFO			
Asset Name:	Panel 1	**Condition Designation:**	N/A
Asset Class:	Series Reactor	**Serviceability:**	N/A
Location:	None – None – None		

PHOTOS

COMMENTS: N/A

UTIL 2

BASIC INFO			
Asset Name:	UTIL 2	**Condition Designation:**	N/A
Asset Class:	Utility	**Serviceability:**	N/A
Location:	None – None – None		

PHOTOS


COMMENTS: N/A

A1


BASIC INFO			
Asset Name:	A1	**Condition Designation:**	N/A
Asset Class:	Panelboard	**Serviceability:**	N/A
Location:	None – None – None		

PHOTOS


IR PHOTOS




H2_visual



H2



H1_visual



H1

COMMENTS: N/A