

Report

Job	11125
Piecemark:	undefined
Type of Inspection	Fit-up
Inspector:	Josue
Fabricator:	Juan
Non Conformance:	No
Fit-Up Inspection	PASS

Inspection Criteria

Is all material correct and alligning with piece details? (size, spec, grade, all thickness ...)	Yes
--	-----

Are all components located accurately to the piece details?	Yes
---	-----

Are all beam copes radiused and smooth?	Yes
---	-----

Are all hole and slots sized and located properly?	N/A
--	-----



