

## Report

Job:	11125
Piecemark:	undefined
Type of Inspection	Fit-up
Inspector:	Josue
Fabricator:	Juan
Non Conformance:	No
Fit-Up Inspection:	PASS

### Inspection Criteria

Is all material correct and alligning with piece details? (size, spec, grade, all thickness ...)	Yes
Are all components located accurately to the piece details?	Yes
Are all beam copes radiused and smooth?	Yes
Are all hole and slots sized and located properly?	Yes

### Comments

Ojfmf. krnweijrnewrjgbgyu guyopjkkjjkj

