

Report

Job:	11125
Piecemark:	MISC 13A1
Type of Inspection	Fit-up
Inspector:	Josue
Fabricator:	Juan
Non Conformance:	No
Fit-Up Inspection:	In Progress

Inspection Criteria

Is all material correct and alligning with piece details? (size, spec, grade, all thickness ...)	Yes
Are all components located accurately to the piece details?	No
Are all beam copes radiused and smooth?	N/A
Are all hole and slots sized and located properly?	Yes

Comments

Uhiuhuh h hypha buuh u