

## Report

Job:	11125
Piecemark:	undefined
Type of Inspection	Fit-up
Inspector:	Josue
Fabricator:	Juan
Non Conformance:	No
Fit-Up Inspection:	In Progress

### Inspection Criteria

Is all material correct and alligning with piece details? (size, spec, grade, all thickness ...)	N/A
Are all components located accurately to the piece details?	No
Are all beam copes radiused and smooth?	N/A
Are all hole and slots sized and located properly?	No

### Comments

Joiigoidsg got heotrrlkl

