

Report

Job	11125
Piecemark:	undefined
Type of Inspection	Fit-up
Inspector:	Paulinno
Fabricator:	Pedro
Non Conformance:	No
Fit-Up Inspection	In Progress


Inspection Criteria

Is all material correct and alligning with piece details? (size, spec, grade, all thickness ...)	N/A
--	-----

Are all components located accurately to the piece details?	Yes
---	-----

Are all beam copes radiused and smooth?	Yes
---	-----

Are all hole and slots sized and located properly?	No
--	----



Comments

Update 2 pictures add my picture