

Report

Job	11125
Piecemark:	undefined
Type of Inspection	Fit-up
Inspector:	Josue
Fabricator:	Juan
Non Conformance:	No
Fit-Up Inspection	In Progress

Inspection Criteria

Is all material correct and alligning with piece details? (size, spec, grade, all thickness ...)	No
Are all components located accurately to the piece details?	No
Are all beam copes radiused and smooth?	N/A
Are all hole and slots sized and located properly?	No





Comments

Hj. F nfjskf ka. K sfj snf nfkjds f sfjsdfk ksjsmflkmlskflf. kdjfsdf