



B GND CONTACT




R GND CONTACT







Engineer:	RF DRX		
Drawn by:			
Rev Ctr:	TITLE:		
Doc Ctr Ctr:	A8_ISTOR		
Proj Instr Ctr:			
QA Ctr:	REV	Drawing Number:	

ALL INFORMATION CONTAINED HEREIN IS UNCLASSIFIED EXCEPT WHERE SHOWN OTHERWISE

CP PART (S333)




CP PMIC




REV0.0	0000
REV0.1	0001
REV0.2	0010
REV1.0A	0011
REV0.3	0100
REV1.0A	0101
REV0.5	1001


CP JTAG










CP / CP PMIC
AB_ISTOR




AP DECAP.



0000	REV0.0
0001	REV0.1
0010	REV0.2
0011	REV0.3
0100	REV0.4
0101	REV0.5

[illegible]






AUDIO



```
user89|swcad89|10.253.20.115|20160920-153049
```


VX_Setup(2016-01-20)_HHP



Model :	
Revision :	
Manufacture Count :	
Charge :	
Contact :	
Date :	
Routing :	
Resin :	

AON1605(TR7001) : IT'S Wrong Polar
ity possibility. Check the Pin1

VX_Setup(2016-01-20)_HHP


		○	
		⊙	
		⊗	
		⊕	
		□	
		⊞	
		⊠	
		+	
		X	

		○	
		⊙	
		⊗	
		⊕	
		□	
		⊞	
		⊠	
		+	
		X	

		○	
		⊙	
		⊗	
		⊕	
		□	
		⊞	
		⊠	
		+	
		X	

		○	
		⊙	
		⊗	
		⊕	
		□	
		⊞	
		⊠	
		+	
		X	

		⊙	
		⊗	
		⊕	
		⊙	
		⊗	
		⊕	
		□	
		⊞	
		⊠	
		+	
		X	



AON1605(TR7001) : IT'S Wrong Polar
ity possibility. Check the Pin1

Model :
Revision :
Manufacture Count :
Charge :
Contact :
Date :
Routing :
Resin :