

استلام من ارمين
عبدالله الى دافود

VEHICLE CONDITION CHECKLIST





Plate #:	6098 VUD	Current User:	Erwin Baldi weza
Model & make:	2021	Employee #:	2441153817
Rental company Name:	الحبر ابيار	Location:	

Indicate any damage to the vehicle in the space provided using your own words or the following legend. If None write None

H - Hairline Scratch	PT - Pitted	T - Torn	B - Bent	GC - Glass Cracked	M - Missing
SM - Smashed	R - Rusty	CR - Creased	S - Scratched	ST - Stained	BR - Broken
					D - Dented

Indicate any damage to the vehicle in the space provided using your own words or the following legend. If None write None

H - Hairline Scratch	PT - Pitted	T - Torn	B - Bent	GC - Glass Cracked	M - Missing
SM - Smashed	R - Rusty	CR - Creased	S - Scratched	ST - Stained	BR - Broken
					D - Dented

 <p>FRONT</p>	<p>1</p> <p>2</p> <p>3</p> <p>4</p> <p>5</p>	 <p>BACK</p>	<p>6</p> <p>7</p> <p>8</p> <p>9</p> <p>10</p>
 <p>DRIVER'S SIDE</p>	<p>11</p> <p>12</p> <p>13</p> <p>14</p> <p>15</p>	 <p>PASSENGER'S SIDE</p>	<p>16</p> <p>17</p> <p>18</p> <p>19</p> <p>20</p> <p>21</p>

INTERIOR					
	<input type="checkbox"/> CLEAN	<input type="checkbox"/> AVERAGE	<input type="checkbox"/> DIRTY		
	Good	Worn	Burns	Rips	Stain
Front Carpet	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Rear Carpet	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Front Seat	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Rear Seat	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Headliner	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Door Panels	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Dash	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	<input type="checkbox"/> Dent	<input type="checkbox"/> Crack	<input type="checkbox"/> Holes		



MECHANICAL					
Engine	<input type="checkbox"/> Smooth	<input type="checkbox"/> Rough	<input type="checkbox"/> Knock		
Trans / Clutch	<input type="checkbox"/> Seems OK	<input type="checkbox"/> Slips			
Air	<input type="checkbox"/> Blows Hot				
Brakes	<input type="checkbox"/> Seems OK	<input type="checkbox"/> Difficult			
Exhaust	<input type="checkbox"/> Seems OK	<input type="checkbox"/> Needs Replacement			
Power Malfunction	<input type="checkbox"/> Windows	<input type="checkbox"/> Seats	<input type="checkbox"/> Locks	<input type="checkbox"/> Roof	
Sound Equip.	<input type="checkbox"/> Inoperative				
Tires	Right Front	Left Front	Right Rear	Left Rear	Spare
Good					<input type="checkbox"/> Missing
Fair					<input type="checkbox"/> Included
Poor					

First Aid Kit	<input type="checkbox"/>	Tool Kit	<input type="checkbox"/>	Jack set	<input type="checkbox"/>
---------------	--------------------------	----------	--------------------------	----------	--------------------------

Please attach 360-degree photos of vehicle.

Handover By:

Checked/Received:

Name:	Erwin Baldi weza	Name:	Dawood Amer
Employee #:	2441153817	Employee #:	2343304727
Signature		Signature	
Date:	02-04-2024	Date	2-4-2024

تم التسليم بواسطة
الطبيب التقيي ام ادم
اسم

Declaration by user

It is confirmed that vehicle is check by me and all the damages/problems listed above are real, and I am responsible for all these damages/problems in the vehicle and cost to fix these damages/problem shell deduct from my salary.

Name: Erwin Baldiweea

Employee #: 24414153817

Signature: 