Work Order

Properties: Emory Woods Apartments - 2085 Powell Ln Decatur, GA 30033
Units: 2158ND03
Tenants: All
Vendors: All
Assigned User: All
Created By: All
Priority: All
From Inspection: All
Current Estimate Approval Status: All
Current Work Order Status: New, Estimate Requested, Estimated, Assigned, Scheduled, Work Done, and Completed
Work Order Type: Unit Turn, Resident, and Internal
Unit Turn Category: All
Status Date: Created On 01/01/2026 - 10/07/2026

Property	Priority	Work Order Type	Work Order Number	Job Description	Status	Vendor	Unit	Primary Resident	Created At	Scheduled Start	Scheduled End	Work Done On	Completed On	Recurring
Emory Woods Apartments - 2085 Powell Ln Decatur, GA 30033														
Emory Woods Apartments - 2085 Powell Ln Decatur, GA 30033	Normal	Internal	24890	A/C not cooling; outside pipe was freezing up, resident turned off to thaw.	Completed	HVAC	2158ND03	Sucharski, Todd M.	08/20/2026	08/20/2026 at 09:30 AM	08/20/2026 at 10:00 AM	08/20/2026	10/02/2026	No
Emory Woods Apartments - 2085 Powell Ln Decatur, GA 30033	Normal	Internal	25068	Repair and correct the following code compliance violations: 1. Kitchen Sink Leak: Repair the plumbing leak underneath the kitchen sink, which is leaking into the base cabinet. Replace any wood shelving or other cabinet materials damaged by the leak. 2. Base Cabinets: Stabilize and secure the kitchen base cabinets. Install replacement cabinet doors for any missing or damaged doors and cabinet components. 3. Bathroom Plumbing and Ceiling: Repair the plumbing leak in the bathroom and repair any kitchen ceiling	Completed	Property Management	2158ND03	Sucharski, Todd M.	09/14/2026	09/15/2026		09/17/2026	10/02/2026	No

Work Order

Property	Priority	Work Order Type	Work Order Number	Job Description	Status	Vendor	Unit	Primary Resident	Created At	Scheduled Start	Scheduled End	Work Done On	Completed On	Recurring
				damage. (Georgie) 4. Rodent Activity: Address the reported rodent activity in the kitchen by placing appropriate bait and sealing all visible access points and openings that may allow rodents to enter the apartment. **Please take before and after photo's of the work**										
Total														