

SERTİFİKALAR



Certificates
شهادات

KEMA

TEST REPORT

Applicant : GERSAN ELEKTRİK TİC. VE SAN. A.Ş.
Tuzla Mermerciler Organize Sanayi Bölgesi Aydınli Mah.
TEM Yanyol Cad. No: 6 Tuzla
İSTANBUL, Türkiye

Application date : 2015-12-14

Order number : 2089974.13-QUA/CPC

Subject : IP43 test on distribution box

Trade name : GERSAN
Type : GDK-3

Arnhem, February 6, 2006

Manufacturer/Factory-location:
GERSAN ELEKTRİK TİC. VE SAN. A.Ş, Tuzla Mermerciler Organize Sanayi Bölgesi
Aydınli Mah., TEM Yanyol Cad. No: 6 Tuzla, İSTANBUL

Test requirements : EN 60529:1991 + Amendment 1:2000

Conclusion : as far as investigated, the distribution box complies with
the specified requirements (see page 2).

Tested by : Gaye Akturk / P.G.J. Wouters

Checked by : P.G.M. Roelofs


Products may not be provided with one of our approval marks, nor put on the market as approved on the basis of this report.

© Copyright KEMA Quality B.V. Publication in total or in part and/or reproduction in whatever way of the contents of this report is not allowed unless permission has been explicitly given either in this report or previous letter.

KEMA Quality B.V. Utrechtseweg 310, 6812 AR Arnhem. P.O. Box 5185, 6802 ED Arnhem, The Netherlands Telephone (+31) 26 356 2006. Telefax (+31) 26 352 5800.



SERTİFİKALAR

Certificates
شهادات

Page 2 of 2

2089974-13-QUA/CPC

Product information

Trade name : GERSAN
 Type : GDK-3
 Degree of Protection : IP43
 Description : distribution box

Scope of the testing

The distribution box has been tested according the following clauses of EN 60529:1991, including Amendment 1:2000

- 13.2 : Protection against solid foreign objects (IP4X)
- 14.2.3 : Test for protection against sprayed water (IPX3)

Description of the protection against solid foreign objects test (IP4X)

The probe (rigid steel wire 1,0 mm ^{+0,05} diameter with edges free from burrs) was pushed against any openings of the distribution box with a force of 1,0 N ^{±10%}.

During the test the full diameter of the probe did not pass through any opening.

Description of the test for protection against sprayed water (IPX3)

The test was made by using an oscillating tube, provided with holes over an arc of 60° either side of the centre point. The distribution box was placed at the centre point of the semicircle and the tube oscillated through an angle of 60 ° on either side of the vertical. The time for one complete oscillation was about 4 seconds and the total test duration 5 minutes. After the distribution box had been turned through a horizontal angle of 90 ° the test was continued for a further 5 minutes.

After the test it showed no deposit of water on insulation parts where it could lead to tracking along creepage distances, no water reached live parts and no water entered the distribution box to such an extent that it interfered with correct operation of the product.

Conclusion

The distribution box complies with the IP43 test requirements.