

Water Quality Datasheet

Date: 12/30/25 Weather: foggy, cold Crew: ESH, SMB

Comments: TER was sampled at 38°24'07.4"N 121°38'04.5"W west side of r.c. fields due to flooding
KNG3 was sampled approximately halfway down the field due to flooding.
Pump for being was at LERLS in the canal leading to the pump

Row	SITE	Time (24hr)	Temp (C)	DO (%)	DO (mg/L)	SPC (µS/cm)	TDS (mg/L)	SAL (PSU)	pH	Turb (FNU)	PC (µg/L)	Chl (µg/L)	FDOM (QSU)	Chl-a grab (y/n)	Zoop Score (1-5)	Zoop net (cm)	Zoop Start	Zoop End
1	Cache	8:08	8.864	84.6	9.80	461.3	291.829	0.22	8.06	68.68	0.51	3.19	64.79	N	/	/	—	—
2	FWBN	8:52	10.201	85.1	9.56	136.3	88.581	0.06	7.62	82.56	0.46	1.03	40.07	N	1	30	153060	153708
3	FW1	9:12	10.075	93.4	10.52	135.3	87.930	0.06	7.69	91.77	0.48	1.25	39.47	N	1	30	153710	154388
4	RD22	9:46	9.708	89.7	10.19	134.5	87.438	0.06	7.67	110.66	0.53	1.07	38.24	N	2.5	30	154390	150988
5	YBLR4	10:09	9.741	90.3	10.25	139.1	90.431	0.07	7.70	107.95	0.51	1.05	39.30	N	1.5	30	154990	155535
6	SR3	10:30	9.474	80.9	9.19	138.8	90.215	0.07	7.55	54.10	0.52	2.24	54.70	N	3.5	30	155546	156213
7	Pump for being	10:48	9.071	65.4	7.53	382.7	248.761	0.18	7.56	171.38	1.76	14.65	48.80	N	4	30	156210	156884
8	ALB	11:30	9.734	77.9	8.85	143.6	93.316	0.07	7.54	68.35	0.45	1.58	47.83	N	2.5	30	156878	157518
9	LIS	11:58	9.801	77.4	8.77	138.7	90.183	0.07	7.53	64.17	0.50	1.77	48.74	N	2.5	30	157520	158175
10	STTD	12:33	9.618	71.6	8.15	152.7	99.223	0.07	7.45	75.01	0.56	4.35	50.74	N	3.0	30	158180	158770
11																		
12	UCD	Sites below				Crew: CS, DC, NJ												
13	KLWW	8:20	9.70	57.3	6.50	427	277	0.21	7.64	55.4	0.38	5.71	77.0	N	—	—	—	—
14	KNG3	8:55	9.67	56.5	6.41	427	277	0.21	7.61	58.5	0.36	4.94	76.4	N	2	30	128182	128509
15	TEW	11:20	9.64	65.6	7.45	165.6	107.66	0.08	7.34	62.42	0.36	65.59	52.32	N	3	30	128528	128899
16	TER	12:55	9.16	69.8	8.01	205.1	133.29	0.10	7.46	66.25	0.32	3.51	53.61	N	4	30	128905	129078
17																		
18																		

Entry date: Entered by: QC date: QC'ed by: