379 Bethesda Road

12/07/2023 – NOV issued by Officer Lawson

01/23/2024 – [redacted] called EE – call was forwarded to Officer Lawson

05/21/2024 – Certified Mail to Each Owner Listed on Property (Assessor's Page)

REDACTED FOR THE PUBLIC COPY

[redacted]

05/21/2024 – The condemned placard and the NOVS placed on the structure

06/04/2024 – The structure was tested for Asbestos

06/24/2024 – [redacted] attempted to pull a demolition permit but due to him not being an owner he was not allowed to pull a demolition permit

08/13/2024 – Deed from [redacted] to [redacted] filed in ROD

08/19/2024 – A Stop Work Order was issued for the property due to the home containing asbestos and being demolished without a permit and lack of proper protocols to handle asbestos removal

08/22/2024 – Demtek was issued a demolition permit

08/26/2024 – Structure was demolished by Demtek

Asbestos Testing -	**$ 1,800.00**
Removal of Asbestos and well capped off -	**$ 35,450.00**
Asbestos Air Monitoring -	**$ 3,100.00**
TOTAL:	**$ 40,350.00**