Drawing No.:

Cust./Mach. No.:

Loc. of check:

Order No.:

Condition:

GBT10095

Tip

Gear Profile/Lead

Operator:

Module m

No. of teeth

Pressure angle

Base Cir.-Ø db

PROFILE

huriping

23

18.5°

27.5°

46.0961mm

25.969°

Face Width:

Length Ev. Lß

Stylus-Ø

right flank

Appr. Length M1

Add.Mod.Coeff

1.9mm Length Ev. La

15.05.2022

17:51

26.72 °

48.16mm

5.79°

(#5)1mm

0

56mm

P 40 6G

left flank

GST0429_05 4.18.0 0

E3000144 G3.2 AC


CE057032A3-QLH1


KLINGELNBERG





Gear Spacing

Prog.No.: GS	0429 <u>05 4.18.0</u> 0	P 40	6G	Operator:	huriping		Date:	15.05.	2022	17:51
Type:	E3000144 G3.2 AC			No. of teeth		23	Pressure	angle		18.5°
Drawing No.:	CE057032A3-QLH1			Module m		1.9mm	Helix an	gle		27.5°
Order No.:	640700214			Loc. of check:	KLINGELNE	ERG				
Cust./Mach. No.: P40 - 602371			Condition:	Intermedi	ate shaft					









Pitch measuring circle:50.069 z=28mm	left f	lank	right flank			
	Act.value Qual	Lim.value Qual.	Act.value Qual.	Lim.value Qual.		
Worst single pitch deviation fp max	1.3	5.0	1.5	5.0		
Worst spacing deviation fu max	1.1	7.0	1.4	7.0		
Range of Pitch Error Rp	2.2		2.8			
Total cum. pitch dev. Fp	6.5	18.0	7.8	18.0		

