Site Inspection Report

Example Facilities Ltd.

Site: Warehouse B, ground floor Inspection date: 12 March 2026
Inspector: Facilities Team Reference: INSP-2026-044



Scale 1:200. Dimensions in metres.

Findings

1. Fire extinguisher missing in the storage room.
2. Emergency exit sign not lit in the loading area.
3. Cable trays in the server room need labelling.

Corrective Actions

Finding	Action	Owner	Due
1	Install a 6 kg extinguisher	Facilities	20 Mar
2	Replace the exit sign battery	Maintenance	15 Mar
3	Label all cable trays	IT	31 Mar

Sign-off: _____