

Test Textile Ltd

Plot 44-46, Sector 3, Karnaphuli EPZ Road
Ashulia, Savar, Dhaka 1341, Bangladesh

T +880 2 7788 4410 F +880 2 7788 4411
merchandising@testtextile.test
BIN 004471003-0201 · BGMEA Reg. 3318
Bond Licence 18/Cus/Bond/2019

FABRIC INSPECTION REPORT — 4-POINT SYSTEM

ASTM D5430 · lot HL-L1-CHM · challan ZJH-DC-8842

Report no	FI-FAB-2815-01	Lot received	60 rolls · 1,567.0 kg
Inspection date	2026-11-13	Rolls inspected	12 (20%)
Material	FAB-FLC-280 brushed fleece 280 g/m²	Acceptance limit	20 points per 100 sq yd
Supplier	Zhejiang Hualing Knitting Co., Ltd	Width	185 cm (72.8 in) tubular
Colour	Charcoal Melange	Bonded	yes — UD UD-2026-058

Roll	Shade	Yards inspected	Defect points	Points / 100 sq yd	Verdict
R-F-03	A	128	9	3.5	pass
R-F-08	A	131	14	5.3	pass
R-F-12	A	126	6	2.4	pass
R-F-17	A	129	24	9.2	FAIL
R-F-21	A	134	11	4.1	pass
R-F-26	A	127	17	6.6	pass
R-F-33	A	130	8	3.0	pass
R-F-39	B	128	13	5.0	pass
R-F-44	B	132	27	10.1	FAIL
R-F-49	B	129	12	4.6	pass
R-F-54	B	126	15	5.9	pass
R-F-58	B	131	22	8.3	FAIL

Result

	Rolls
Inspected	12
Passed	9
Failed	3
Lot verdict	ACCEPTED WITH SEGREGATION

Defects recorded

R-F-17 — running slub 3.2 m from head, needle line 1.8 m; 24 pts.
R-F-44 — oil stain patch 40 × 12 cm, hole at 68 m; 27 pts.
R-F-58 — barré across full width in three places; 22 pts.

Shade continuity checked against the approved swatch under D65.
R-F-39 onward reads half a step darker and is grouped B.

Decision. The lot is accepted for the passing rolls. R-F-17, R-F-44, R-F-58 are quarantined for claim against the mill under clause 4 of the proforma and must not be issued to cutting. Shade groups A and B are to be issued to separate lays; no garment may carry both.

Fabric QC inspector

Quality manager

Store — segregation confirmed

TEST FIXTURE — this document was generated for FabricXAI platform testing. Nordkap Apparel AB and every counterparty named here are invented. It is not real business paper and carries no legal meaning.