

CERTIFICATE OF THOROUGH EXAMINATION

Date of Thorough Examination : 24 June 2026		Date of Report : 29 June 2026		Report Number : IVG.02/IRP/26/VI/078	
Name and Address of employer for whom the thorough examination was made : PT Meindo Elang Indah TCC Batavia Tower One, 27th Floor, Jl. K.H. Mas Mansyur Kav 126, Jakarta			Address of premises at which the examination was made : WS Meindo Balaraja		
Description and identification of the equipment : Excavator Manufacturer : Kobelco Model : SK200-10 Engine Model : HINO J05ETA-KSSE Rated Power : 118 kW/2,000 min Serial Number : YN15425423		Max Capacity 27700 Kg	Date of manufacture if known : 2022	Date of last thorough examination : N/A	
References : Permenaker Nomor 8 Tahun 2020 Keselamatan dan Kesehatan Kerja Pesawat Angkat dan Pesawat Angkut					
Is this the first examination after installation or assembly at a new site or location?		YES ☒ NO ☐		Was the examination carried out:	
If the answer to the above question is YES has the equipment been installed correctly?		YES ☒ NO ☐		Within an interval of 6 months?	
				YES ☐ NO ☒	
				Within an interval of 12 months?	
				YES ☒ NO ☐	
				In accordance with an examination scheme?	
				YES ☐ NO ☒	
				After the occurrence of exceptional circumstances?	
				YES ☐ NO ☒	
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect : (If none state NONE) None					
Is the above a defect which is of immediate danger to persons				YES ☐ NO ☒	
Is the above a defect which is not yet but could become a danger to persons (If YES, state the date by when)				YES by : None	
Particulars of any repair, renewal or alteration required to remedy the defect identified above : None					
Particulars of any tests carried out as part of the examination : (If none state NONE) NDT Report No. IVG.02/IRP/26/VI/078					
IS THIS EQUIPMENT FIT FOR PURPOSE ?				YES ☒ NO ☐	
Name & Qualifications of person making this report : Signature: Agus Sulparman AK3PAPA5/13594/AS.01.04/VI/2025		Name of person authenticating this report : Signature: Armand Zachary Director		Latest date by which next thorough examination must be carried out : 23 June 2027	
Name and address of employer of persons making and authenticating this report : PT Indo Veritas Grup					

INSPECTION REPORT

Customer Name	PT Meindo Elang Indah	Report No.	IVG.02/IRP/26/VI/078
Customer Address	TCC Batavia Tower One, 27th Floor, Jl. K.H. Mas Mansyur Kav 126, Jakarta	Location of Inspection	WS Meindo Balaraja
Method of Inspection	Visual & NDT	Inspection Scheme	Initial / New Inspection
Description	Excavator	Date of Inspection	2026-06-24
Date of Report	2026-06-29		
Description of Equipment			
Equipment Name	Excavator	Manufacturer	Kobelco
Model/ Type	SK200-10	Max Capacity	27700 Kg
Year of Manufactured	2022	Engine Model / Rated Power	HINO J05ETA-KSSE / 118 kW/2,000 min
Serial Number	YN15425423		
Reference			
Reference	Permenaker Nomor 8 Tahun 2020 Keselamatan dan Kesehatan Kerja Pesawat Angkat dan Pesawat Angkut		
Result			
Result of Inspection	Satisfactory	Remarks	N/A
Documentation			
General Overview			
  			

Report Prepared by

Authenticated by



Agus Sulparman
AK3PAPA 5/13594/AS.01.04/VII/2025



Armand Zachary
Director

INSPECTION REPORT

Customer Name	PT Meindo Elang Indah	Report No.	IVG.02/IRP/26/VI/078
Customer Address	TCC Batavia Tower One, 27th Floor, Jl. K.H. Mas Mansyur Kav 126, Jakarta	Location of Inspection	WS Meindo Balaraja
Method of Inspection	Visual & NDT	Inspection Scheme	Initial / New Inspection
Description	Excavator	Date of Inspection	2026-06-24
Date of Report	2026-06-29		

Documentation

Cabin View



View of Wheels / Moving Devices



INSPECTION REPORT

Customer Name	PT Meindo Elang Indah	Report No.	IVG.02/IRP/26/VI/078
Customer Address	TCC Batavia Tower One, 27th Floor, Jl. K.H. Mas Mansyur Kav 126, Jakarta	Location of Inspection	WS Meindo Balaraja
Method of Inspection	Visual & NDT	Inspection Scheme	Initial / New Inspection
Description	Excavator	Date of Inspection	2026-06-24
Date of Report	2026-06-29		

Documentation

View of Wheels / Moving Devices



INSPECTION REPORT

LAIR&D20002

Customer Name	PT Meindo Elang Indah	Report No.	IVG.02/IRP/26/VI/078
Customer Address	TCC Batavia Tower One, 27th Floor, Jl. K.H. Mas Mansyur Kav 126, Jakarta	Location of Inspection	WS Meindo Balaraja
Method of Inspection	Visual & NDT	Inspection Scheme	Initial / New Inspection
Description	Excavator	Date of Inspection	2026-06-24
Date of Report	2026-06-29		

Documentation

Engine



Hydraulic System



INSPECTION REPORT

LAIR&D20002

Customer Name	PT Meindo Elang Indah	Report No.	IVG.02/IRP/26/VI/078
Customer Address	TCC Batavia Tower One, 27th Floor, Jl. K.H. Mas Mansyur Kav 126, Jakarta	Location of Inspection	WS Meindo Balaraja
Method of Inspection	Visual & NDT	Inspection Scheme	Initial / New Inspection
Description	Excavator	Date of Inspection	2026-06-24
Date of Report	2026-06-29		

Documentation

Radiator and Cooling System



Boom View



INSPECTION REPORT

LAIR&D20002

Customer Name	PT Meindo Elang Indah	Report No.	IVG.02/IRP/26/VI/078
Customer Address	TCC Batavia Tower One, 27th Floor, Jl. K.H. Mas Mansyur Kav 126, Jakarta	Location of Inspection	WS Meindo Balaraja
Method of Inspection	Visual & NDT	Inspection Scheme	Initial / New Inspection
Description	Excavator	Date of Inspection	2026-06-24
Date of Report	2026-06-29		

Documentation

Boom View



INSPECTION REPORT

LAIR&D20002

Customer Name	PT Meindo Elang Indah	Report No.	IVG.02/IRP/26/VI/078
Customer Address	TCC Batavia Tower One, 27th Floor, Jl. K.H. Mas Mansyur Kav 126, Jakarta	Location of Inspection	WS Meindo Balaraja
Method of Inspection	Visual & NDT	Inspection Scheme	Initial / New Inspection
Description	Excavator	Date of Inspection	2026-06-24
Date of Report	2026-06-29		

Documentation

Manufacturer Data Plate & Inspection Tag



Safety Apparatus



NON-DESTRUCTIVE TESTING REPORT

NR0014

Customer Name	PT Meindo Elang Indah	Report No.	IVG.02/IRP/26/VI/078			
Customer Address	TCC Batavia Tower One, 27th Floor, Jl. K.H. Mas Mansyur Kav 126, Jakarta	Date of Test	2026-06-24			
Job Location	WS Meindo Balaraja	Description	NDT Excavator			
Method and Criteria						
Quality Requirement	ASTM E 709	Acceptance Criteria	AWS D1.1 2025			
Method Applied	Magnetic Particle Test	Material Type	Ferromagnetic Metal			
Welding Process	As Welded	Surface Preparation	Wire Brushed			
Surface Temperature (Celcius)	35,2	Light Intensity (Lux)	1105			
Post Cleaning	Cleaner / Solvent Wipe					
Test Equipment Details						
Test Equipment	Permanent Yoke	Equipment Serial Number	PY140CM			
Calibration Date	2025-09-26	Technique	Wet Continous			
Test Consumable (Name/Code/Brand/Batch/Expiry)	White Contrast/MR72/MRChemie/2212003/Dec-27 Magnetic Particle/MR76S/MRChemie/2409001/Sep-29					
Result						
No.	Description	Test Location / Joint	Thickness	Interpretation	Remarks	Type of Indication
1	Excavator YN15425423	Bucket Left Pivot		Accepted	N/A	N/A
2	Excavator YN15425423	Bucket Right Pivot		Accepted	N/A	N/A
3	Excavator YN15425423	Middle Joint		Accepted	N/A	N/A

Report Prepared by

Authenticated by



Agus Sulparman
AK3PAPA 5/13594/AS.01.04/VII/2025



Armand Zachary
Director

NON-DESTRUCTIVE TESTING REPORT

NR0014

Customer Name	PT Meindo Elang Indah	Report No.	IVG.02/IRP/26/VI/078
Customer Address	TCC Batavia Tower One, 27th Floor, Jl. K.H. Mas Mansyur Kav 126, Jakarta	Date of Test	2026-06-24
Job Location	WS Meindo Balaraja	Description	NDT Excavator

Documentation for NDT



Bucket Left Pivot



Bucket Right Pivot



Middle Joint