

Annex C - SAR Test Setup Photos

Description: Extremity Front with 0mm gap




Description: Extremity Back with 0mm gap



Description: Extremity Left with 0mm gap




Description: Extremity Right with 0mm gap




Annex D EUT Photos


(1) EUT Photo




(2) EUT Photo




(3) EUT Photo




(4) EUT Photo




(5) EUT Photo




(6) EUT Photo












(9) EUT Photo






(11) EUT Photo








(13) EUT Photo




(14) EUT Photo





(15) EUT Photo





(17) EUT Photo





(19) EUT Photo



