


 Prüfbericht - Nr.:
 17037987 001
 Seite 47 von 49


 Test Report No.
 Page 47 of 49

7. Photographs of the Test Set-Up

Photograph 1: Set-up for Radiated Emissions below 30MHz










Prüfbericht - Nr.: 17037987 001

Test Report No.

Seite 48 von 49 *Page 48 of 49*

Photograph 3: Set-up for Radiated Emissions for 1 – 18GHz



Photograph 4: Set-up for Radiated Emissions for 18 – 26.5GHz

