

Report No.: CQAS20190700608E-03

Photographs

7.1 Conducted Emission Test Setup








Report No.: CQAS20190700608E-03

7.2 Radiated Emission Test Setup

Below 1GHz:





Above 1GHz

