

Produkte Products

Prüfbericht - Nr.:
Test Report No.

10043758 001

Seite 32 von 36 *Page 32 of 36*

7. Photographs of the Test Set-Up

Photograph 1: Set-up for Spurious Emissions (Front View)






Produkte Products

Prüfbericht - Nr.: 10043758 001 Test Report No.

Seite 33 von 36 *Page 33 of 36*

Photograph 2: Set-up for Spurious Emissions (Back View 1)





Produkte Products


Prüfbericht - Nr.: 10043758 001
Test Report No.

Seite 34 von 36 *Page 34 of 36*

Photograph 3: Set-up for Spurious Emissions (Back View 2)



Photograph 4: Set-up for Conducted testing








 Prüfbericht - Nr.:
 10043758 001
 Seite 35 von 36

 Test Report No.
 Page 35 of 36

Photograph 5: Set-up for for Mains Conducted testing Back



Photograph 6: Set-up for for Mains Conducted testing Front

