

 Prüfbericht - Nr.:
 17050207 001
 Seite 52 von 54


 Test Report No.
 Page 52 of 54

7. Photographs of the Test Set-Up

Photograph 1: Set-up for Spurious Emissions for below 30MHz










Prüfbericht - Nr.: 17050207 001

Test Report No.

Seite 53 von 54 *Page 53 of 54*

Photograph 3: Set-up for Spurious Emissions for 1 - 18GHz



Photograph 4: Set-up for Spurious Emissions for 18 - 26.5GHz

