


Prüfbericht - Nr.: 50087264 001

Test Report No.


Seite 19 von 21 Page 19 of 21

## 7 Photographs of the Test Set-Up

Photograph 1: Set-up for Radiated Spurious Emission (9kHz ~ 30MHz)



Photograph 2: Set-up for Radiated Spurious Emission (30MHz~1GHz)





Prüfbericht - Nr.: 50087264 001

Test Report No.

Seite 20 von 21 Page 20 of 21

Photograph 3: Set-up for Radiated Spurious Emission (1GHz ~ 18GHz)



Photograph 4: Set-up for Radiated Spurious Emission above 18GHz

