




PHOTOGRAPHS OF TEST SETUP

Test model No.:CD52



Radiated spurious emission Test Setup-1(Below 30M)



Radiated spurious emission Test Setup-2(Below 1GHz)



Report No. : EED32L00291601 Page 52 of 60



Radiated spurious emission Test Setup-3(Above 1GHz)



Radiated spurious emission Test Setup-4(Above 1GHz)
There is absorber on the ground floor



















Report No.: EED32L00291601

Page 53 of 60



























































