



8. Test Setup Photographs

8.1. Spurious Radiated Emissions, 30 kHz to 1 GHz - Front View








Test Number: 271-18 Issue Date: 7/23/2018

8. Test Setup Photographs

8.2. Spurious Radiated Emissions, 30 kHz to 30 MHz - Rear View







8. Test Setup Photographs

8.3. Spurious Radiated Emissions, 30 MHz to 1 GHz - Rear View







8. Test Setup Photographs

8.4. Radiated Emissions above 1 GHz - Front View








8. Test Setup Photographs

8.5. Radiated Emissions 1 to 18 GHz - Rear View








8. Test Setup Photographs

8.6. Radiated Emissions Above 18 GHz - Rear View







8. Test Setup Photographs

8.7. Product Conducted Measurements 1 of 3



8.8. Product Conducted Measurements 2 of 3








Test Number: 271-18 Issue Date: 7/23/2018

8. Test Setup Photographs

8.9. Product Conducted Measurements 3 of 3







Test Number: 271-18 Issue Date: 7/23/2018

8. Test Setup Photographs

8.10. Product Conducted Emissions Measurements - Front

