

REPORT No.: SZ16050106S01A


14. ANNEX D EUT TEST POSITION PHOTOS

1. Body-worn condition



2. Face upward condition







3. Edge A



4. Edge B





REPORT No.: SZ16050106S01A

5. Liquid Level Photo Body Liquid



Liquid depth:15.5cm





6. EUT Front View



7. EUT Back View



***** END OF REPORT ****