

 Prüfbericht - Nr.:
 10047908 001
 Seite 38 von 41


 Test Report No.
 Page 38 of 41

7. Photographs of the Test Set-Up

Photograph 1: Set-up for Spurious Emissions (Front View)



Photograph 2: Set-up for Spurious Emissions (Back View 1)






 Prüfbericht - Nr.:
 10047908 001
 Seite 39 von 41

 Test Report No.
 Page 39 of 41

Photograph 3: Set-up for Spurious Emissions (Back View 2)



Photograph 4: Set-up for Conducted testing






 Prüfbericht - Nr.:
 10047908 001
 Seite 40 von 41

 Test Report No.
 Page 40 of 41

Photograph 5: Set-up for for Mains Conducted testing Back



Photograph 6: Set-up for for Mains Conducted testing Front

