


Products

 Prüfbericht - Nr.:
 10051665 001
 Seite 46 von 50

 Test Report No.
 Page 46 of 50

7. Photographs of the Test Set-Up

Photograph 1: Set-up for Spurious Emissions (Front View)







 Prüfbericht - Nr.:
 10051665 001
 Seite 47 von 50

 Test Report No.
 Page 47 of 50

## Photograph 2: Set-up for Spurious Emissions (Back View 1)



Photograph 3: Set-up for Spurious Emissions (Back View 2)





Prüfbericht - Nr.: 10051665 001

**Seite 48 von 50** *Page 48 of 50* 

Test Report No.

## Photograph 4: Set-up for Conducted testing



Photograph 5: Set-up for for Mains Conducted testing Back





Products

Prüfbericht - Nr.: 10051665 001

**Seite 49 von 50** *Page 49 of 50* 

Test Report No.

## **Photograph 6: Set-up for for Mains Conducted testing Front**

