Prüfbericht - Nr.:
 10052881 001
 Seite 27 von 30

 Test Report No.
 Page 27 of 30

7. Photographs of the Test Set-Up

Photograph 1: Set-up for Spurious Emissions (Front View)







Prüfbericht - Nr.: 10052881 001
Test Report No.

Seite 28 von 30 *Page 28 of 30*

Photograph 2: Set-up for Spurious Emissions (Back View 1)



Photograph 3: Set-up for Spurious Emissions (Back View 2)





Products

Prüfbericht - Nr.: 10052881 001

Seite 29 von 30 *Page 29 of 30*

Test Report No.

Photograph 4: Set-up for Conducted testing

