


 Prüfbericht - Nr.:
 1609191618-001
 Seite 23 von 29

 Test Report No.:
 Page 23 of 29

## 6 Photographs of the Test Set-Up

Photograph 1: photo of the EUT tested in the range below 30 MHz with Loop Antenna







 Prüfbericht - Nr.:
 1609191618-001
 Seite 24 von 29

 Test Report No.:
 Page 24 of 29

## Photograph 2: photo of the EUT tested in the range 30-1000 MHz with BiLog Antenna



Photograph 3: photo of the EUT tested in the range 1000-12750 MHz with Horn Antenna





Prüfbericht - Nr.: 1609191618-001

Test Report No.:

**Seite 25 von 29** *Page 25 of 29* 

## Photograph 4: photo of the EUT in the AC Mains Conducted Emission test

