

 Prüfbericht - Nr.:
 50270936 001
 Seite 29 von 32


 Test Report No.
 Page 29 of 32

## 7. Photographs of the Test Set-Up

**Photograph 1: Set-up for Spurious Emissions (Front View)** 



Photograph 2: Set-up for Spurious Emissions (Back View 1)






Prüfbericht - Nr.: 50270936 001


Test Report No.

**Seite 30 von 32** *Page 30 of 32* 

Photograph 3: Set-up for Spurious Emissions (Back View 2)



Photograph 4: Set-up for Conducted testing






 Prüfbericht - Nr.:
 50270936 001
 Seite 31 von 32

 Test Report No.
 Page 31 of 32

## Photograph 5: Set-up for for AC Mains (Back)



Photograph 6: Set-up for for AC Mains (Front)

