

Products


Prüfbericht - Nr.: 10052944 001 Seite 30 von 34

Test Report No.

Page 30 of 34

## 7. Photographs of the Test Set-Up

Photograph 1: Set-up for Spurious Emissions (Front View)







 Prüfbericht - Nr.:
 10052944 001
 Seite 31 von 34

 Test Report No.
 Page 31 of 34

## Photograph 2: Set-up for Spurious Emissions (Back View 1)



Photograph 3: Set-up for Spurious Emissions (Back View 2)





Products

Prüfbericht - Nr.: 10052944 001 Test Report No.

52944 001

**Seite 32 von 34** *Page 32 of 34* 

## Photograph 4: Set-up for Conducted testing





Prüfbericht - Nr.: 10052944 001 Test Report No.

**2944 001** Seite 33 von 34 Page 33 of 34

**Photograph 5: Set-up for for Mains Conducted testing Back** 



**Photograph 6: Set-up for for Mains Conducted testing Front** 

