Produkte Products

 Prüfbericht - Nr.:
 50160881 001
 Seite 31 von 37

 Test Report No.
 Page 31 of 37

# 7. Photographs of the Test Set-Up

Photograph 1: Set-up for Spurious Emissions (Front View 1)






Prüfbericht - Nr.: 50160881 001


Test Report No.

**Seite 32 von 37** *Page 32 of 37* 

### **Photograph 2: Set-up for Spurious Emissions (Front View 2)**



Photograph 3: Set-up for Spurious Emissions (Back View 1)






 Prüfbericht - Nr.:
 50160881 001
 Seite 33 von 37

 Test Report No.
 Page 33 of 37

### Photograph 4: Set-up for Spurious Emissions (Back View 2)



Photograph 5: Set-up for Spurious Emissions (Back View 3)






 Prüfbericht - Nr.:
 50160881 001
 Seite 34 von 37

 Test Report No.
 Page 34 of 37

# Photograph 6: Set-up for Spurious Emissions (Back View 4)



Photograph 7: Set-up for Conducted testing









Prüfbericht - Nr.: 50160881 001 Test Report No.

**Seite 35 von 37** *Page 35 of 37* 

Photograph 8: Set-up for Conducted testing



Photograph 9: Set-up for Conducted testing





Prüfbericht - Nr.: 50160881 001

Test Report No.

**Seite 36 von 37** *Page 36 of 37* 

# **Photograph 10: Set-up for Mains Conducted testing Front**



Photograph 11: Set-up for Mains Conducted testing Back

