







1625STKmod002_fcc247 C1 Page 16 **of** 49










1625STKmod002_fcc247 C1 Page 17 of 49









1625STKmod002_fcc247 C1 Page 18 **of** 49









1625STKmod002_fcc247 C1 Page 19 **of** 49

Test Setup (Conducted Emissions)

The photographs below show worst case setup for line conducted testing.





Atlas Compliance & Engineering, Inc.
1792 Little Orchard Street
San Jose, CA 95125
Phone 408.971.9743
Fax 408-971-9783
Web www.atlasce.com

Test Setup (Conducted RF)

The photographs below show the test setup for conducted RF testing.

