


Products

 Prüfbericht - Nr.:
 10055561 001
 Seite 29 von 33

 Test Report No.
 Page 29 of 33

Photographs of the Test Set-Up

Photograph 1: Set-up for Spurious Emissions (Front View)







 Prüfbericht - Nr.:
 10055561 001
 Seite 30 von 33

 Test Report No.
 Page 30 of 33

Photograph 2: Set-up for Spurious Emissions (Back View 1)



Photograph 3: Set-up for Spurious Emissions (Back View 2)






Products


Prüfbericht - Nr.: 10055561 001

Test Report No.

Seite 31 von 33 *Page 31 of 33*

Photograph 4: Set-up for Conducted testing








Prüfbericht - Nr.: 10055561 001

Test Report No.

Seite 32 von 33 *Page 32 of 33*

Photograph 5: Set-up for for Mains Conducted testing Back



Photograph 6: Set-up for for Mains Conducted testing Front

