

 Prüfbericht - Nr.:
 10055801 001
 Seite 24 von 27

 Test Report No.
 Page 24 of 27

## 6. Photographs of the Test Set-Up

Photograph 1: Set-up for Spurious Emissions (Front View)






Prüfbericht - Nr.: 10055801 001

Test Report No.

**Seite 25 von 27** *Page 25 of 27* 

Photograph 2: Set-up for Spurious Emissions (Back View TX)



Photograph 3: Set-up for for Mains Conducted testing Back





Products

Prüfbericht - Nr.: 10055801 001

**Seite 26 von 27** *Page 26 of 27* 

Test Report No.

## **Photograph 4: Set-up for for Mains Conducted testing Front**

