

Products

 Prüfbericht - Nr.:
 10054997 001
 Seite 24 von 28

 Test Report No.
 Page 24 of 28

6. Photographs of the Test Set-Up

Photograph 1: Set-up for Spurious Emissions (Front View) (Antenna MV-ALS-AT01)






Prüfbericht - Nr.: 10054997 001


Test Report No.

Seite 25 von 28 *Page 25 of 28*

Photograph 2: Set-up for Spurious Emissions (Back View 1 TX)



Photograph 3: Set-up for Spurious Emissions (Front View) (Antenna MV-ALS-AT02)






Prüfbericht - Nr.: 10054997 001

Seite 26 von 28 *Page 26 of 28*

Test Report No.

Photograph 4: Set-up for Spurious Emissions (Back View 1 TX)



Photograph 5: Set-up for for Mains Conducted testing Back





Products

Prüfbericht - Nr.: 10054997 001
Test Report No.

Seite 27 von 28 *Page 27 of 28*

Photograph 6: Set-up for for Mains Conducted testing Front

