

Annex 3: Internal photographs of EUT to TEST REPORT

No.: 16-1-0180701T09a

#### According to:

### **FCC Regulations**

Part 15.205

Part 15.207

Part 15.209


Part 15.247

for

Viessmann Werke GmbH & Co. KG

## ViCare Thermostat

FCC ID: 2AIZ9-VT0318






<b>TABLE OF</b>	<b>CONTENTS:</b>
-----------------	------------------

1. INTERNAL PHOTOGRAPHS	3
1.1. Equipment Under Test (EUT) Assembly	3




# 1. Internal photographs

# 1.1. Equipment Under Test (EUT) Assembly



Photograph 1: ViCare Thermostat -Housing Top Side




Photograph 2: ViCare Thermostat -Housing Bottom Side





Photograph 3: ViCare Thermostat –Housing Top Side –Display Back




Photograph 4: ViCare Thermostat –Housing Top Side –Display Front





Photograph 5: ViCare Thermostat -Main PCB Top Side




Photograph 6: ViCare Thermostat – Main PCB Bottom Side





Photograph 7: ViCare Thermostat -Main PCB Bottom Side-Conducted Connectors



Photograph 8: ViCare Thermostat -Radio Modules + Onboard Antennas