

Annex 3: Internal photographs of EUT to TEST REPORT

No.: 16-1-0180701T08a

According to:

FCC Regulations

Part 15.205

Part 15.207

Part 15.209

Part 15.247

for

Viessmann Werke GmbH & Co. KG

ViCare Thermostat

FCC ID: 2AIZ9-VT0318






TABLE OF	CONTENTS:
-----------------	------------------

1. INTERNAL PHOTOGRAPHS	3
1.1. Equipment Under Test (EUT) Assembly	3




1. Internal photographs

1.1. Equipment Under Test (EUT) Assembly



Photograph 1: ViCare Thermostat -Housing Top Side




Photograph 2: ViCare Thermostat -Housing Bottom Side





Photograph 3: ViCare Thermostat –Housing Top Side –Display Back




Photograph 4: ViCare Thermostat –Housing Top Side –Display Front





Photograph 5: ViCare Thermostat -Main PCB Top Side




Photograph 6: ViCare Thermostat – Main PCB Bottom Side





Photograph 7: ViCare Thermostat -Main PCB Bottom Side-Conducted Connectors



 ${\bf Photograph~8:~ViCare~Thermostat-Radio~Modules+Onboard~Antennas}$