

Annex 2: External photographs of EUT to TEST REPORT

No.: 16-1-0180701T08a

According to:

FCC Regulations

Part 15.205 Part 15.207

Part 15.207

Part 15.247

ait 15.24

for

Viessmann Werke GmbH & Co. KG

ViCare Thermostat

FCC ID: 2AIZ9-VT0318







TABLE OF CONTENTS:

1. EXTERNAL PHOTOGRAPHS	. 3
1.1. Equipment Under Test (EUT)-Radiated Test Sample	
1.2. Equipment Under Test (EUT)-Conducted Test Sample	
1.3. Auxiliary Equipments (AEs)	
1.4. Equipment Under Test (EUT)-Connections	10



1. External photographs

1.1. Equipment Under Test (EUT)-Radiated Test Sample



Photograph 1: ViCare Thermostat -Front-Top Side




Photograph 2: ViCare Thermostat –Rear-Top Side





Photograph 3: ViCare Thermostat-Back Side



Photograph 4: ViCare Thermostat -Back Side





Photograph 5: ViCare Thermostat –uUSB Connector Side


1.2. Equipment Under Test (EUT)-Conducted Test Sample



Photograph 6: EUT A / AE 6 –Front Top Side with Conducted Connectors



1.3. Auxiliary Equipments (AEs)




Photograph 7: AE 1 - AC/DC µUSB Adapter



Photograph 8: AE 2 - Open Therm Loop Cable





Photograph 9: AE 3 - 12 V DC Power Cable



Photograph 10: AE 4 / AE 8 - μ USB- USB Cable






Photograph 11: AE 5 - Test Laptop with Charger



Photograph 12: AE 5 - Test Laptop Details






Photograph 13: AE 7 - Test Laptop




Photograph 14: AE 7 - Test Laptop Details



1.4. Equipment Under Test (EUT)-Connections



Photograph 15: EUT B + AE 1 + AE 2 + AE 3-Front Side



Photograph 16: EUT B + AE 1 + AE 2 + AE 3 -Back Side