

 Prüfbericht - Nr.:
 50154949 001
 Seite 28 von 31

 Test Report No.
 Page 28 of 31

7. Photographs of the Test Set-Up

Photograph 1: Set-up for Spurious Emissions (Front View)







 Prüfbericht - Nr.:
 50154949 001
 Seite 29 von 31

 Test Report No.
 Page 29 of 31

Photograph 2: Set-up for Spurious Emissions (Back View 1)



Photograph 3: Set-up for Spurious Emissions (Back View 2)





Prüfbericht - Nr.: 50154949 001

Test Report No.

Seite 30 von 31 *Page 30 of 31*

Photograph 4: Set-up for Spurious Emissions (Back View 3)



Photograph 5: Set-up for Conducted testing

